COALESCE CONSTRUCTION LIMITED

PROJECT OVERVIEW

FITZSIMMONS GUILDFORD

INTERIOR REFURBISHMENT / PHOTOGRAPHIC PROFILE



FROM STORAGE ROOMS TO CONTEMPORARY WORKSPACES


COALESCE CONSTRUCTION LIMITED

A considered interior transformation

Conversion of existing ancillary and storage spaces into practical meeting, kitchenette and staff break-out accommodation.




INTERIOR / PROJECT PHOTOGRAPHY



PROJECT DETAIL


Original condition



EXISTING MULTI-USE ROOM



STORED EQUIPMENT AND FURNITURE



ORIGINAL STORAGE ROOM




EARLY WALL PREPARATION

Construction and fit-out




WALL LINING AND INSULATION



WALL PREPARATION AND SERVICES



FEATURE TIMBER INSTALLATION



FEATURE WALL DETAILING

Finishes and fitting out




FLOOR AND WALL FINISHES



KITCHENETTE INSTALLATION




TIMBER FEATURE WALL IN PROGRESS



TIMBER INSTALLATION DETAIL


Completed interiors




LOUNGE AND BREAK-OUT SEATING



NEW THRESHOLDS AND FLOOR FINISHES



FEATURE LIGHTING AND EXPOSED BRICK



TIMBER FEATURE WALL AND MEETING ROOM

Meeting space and kitchenette




FURNISHED MEETING AND DINING SPACE



COMPLETED KITCHENETTE




KITCHENETTE DURING INSTALLATION



PREPARED FLOOR AND EXPOSED BRICK

Before, during and after

The photographic record documents the progression from storage and preparation through construction to completed fitted interiors.



BEFORE



DURING



AFTER

PROJECT: FITZSIMMONS - GUILDFORD

WORKS: INTERNAL REFURBISHMENT AND FIT-OUT

PHOTOGRAPHIC PROJECT OVERVIEW